

Best Practices for Setting Up Your TRU Mixing Station



TRU Mixing Station

brought to you by



RUNYON
SURFACE PREP
RENTAL & SUPPLY


The Ideal Overlay Mixing Station Set-Up:



Equipment Needed:

- (4) CS Unitec Hippo Mixers*
- (3) CS Unitec Pelican Carts*


Miscellaneous Items:

- (12) 5-gallon buckets* 
- Midwest Rake gauge rakes & cams (36" for flat floor, or 24")*

- Shoe-In blunt spiked shoes* 

- Porcupine rollers* for TRU PC 

- (3) Bucket strainers* 

- (3) Bucket strainers* (put inside each Pelican Cart) 

- 55-gallon drums or wheeled trash cans (for mixing water)

- Digital timers

- Weather stripping

- Gorilla Tape

Output:

- 50 - 60 bags/hr per Hippo
- 750-900 sq ft/hr per Hippo
- 3,000 sq ft/hr with (4) Hippos & (3) Pelican carts

Mixing:

- Mixing time will vary slightly...
 - Older Hippos have smaller paddles
 - Current paddle is 15" x 9"
 - Generally, mix for 2-2.5 min after last bag added
- No straining is needed with TRU PC

*Denotes these items are available for purchase through Runyon